1027

Internal File

2001 Annual Report Review

1
()

Permittee:	UtahAmerican Energy Inc.	
Mine Name:	Horse Canyon (Lila Cyn)	
Permit Number:	C/007/013	
Date Report Received:	March 8, 2002	
-		Date Completed ▼
Assigned Reviewers:		
	Dave Darby, Hydrologist	June 30, 2002
	Joe Helfrich, Biologist	June 7, 2002
	Karl R. Houskeeper, Engineer/Inspector KRH by AX	June 19, 2002

<u>Instructions:</u> The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

Assignments:

Inspectors:

Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.

Hydrologists:

Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste

Biologists:

Review Vegetation/Revegetation Success Monitoring, Raptor Survey

Engineers:

Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden,

Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	YES NO		FINDINGS
Cover Sheet			Meets the minimum requirements.
AVS; Legal/ Financial Update			Permit extension request (Lila) under review, information will be updated at this time.
Mine Sequence Map			Mine is inactive at the present time. Horse Canyon Mine is under reclamtion.
Water Monitoring Data			Data was submitted in the water monitoring data base
Precipitation & Climatological Data			Information is provided in the MRP.
Non-Coal Waste report			Horse Canyon mine is not operating and no non coal waste is being generated.
Subsidence Monitoring Data			Mine is inactive at the present time. Horse Canyon Mine is under reclamtion.
Annual Impoundment Certification			Quarterly inspections included for 2001. August 7, 2001 inspection is P.E. Certified.
Annual Overburden, Spoil, Refuse, Floor, etc.		X	Mine is inactive at the present time. Horse Canyon Mine is under reclamtion.
Vegetation Data			Not Required

Internal File

2001 Annual Report Review

SECTIONS TO REVIEW	SUBM YES	ITTED NO	FINDINGS
Revegetation Success Monitoring			Not Required
Raptor Survey			Not Required
Other Information			Not Required